



Position	Antal	Type nr.	Beskrivelse	PG
1	1	316062280	Armature compl., 230V	36
2	1	311012230	Field compl.	28
3	1	344493180	KABEL MED STIK	27
4	1	344097360	TYLLE	11
5	1	343362490	KABELKLEMME 710	12
6	1	141117060	SELVSK,SKRUE ST 4.2X22	12
7	2	344498880	Strand compl.	11
8	1	315013660	MOTORHUS F/ WE 9-125 QUICK	22
9	1	343430940	AFBRYDER ARM	11
10	1	343397810	Switch slide,H/L	11
11	1	143115690	Ball bearing,6x19x6	13
12	1	344097870	GUMMI BØSNING	11
13	1	343436590	AFBØJNINGSSKÆRM	13
14	1	143114880	KUGLELEJE	14
15	1	343430910	MOTORKAPPE WE 9- 125 QUICK	20
16	3	141113180	SKRUE	11
17	4	141117060	SELVSK,SKRUE ST 4.2X22	12
19	1	315202620	Bearing flange	25
20	1	344160400	GAFFELNØGLE 17 MM	16
22	1	344099150	Handle	19
23	1	316051730	Spindle head compl.	38
24	1	343082840	Electronic unit,230V	31
25	1	343409640	Switch	19
26	2	316046890	Brush holder compl. cut out	22
27	1	316046900	Carbon brush set cut-off	22
28	1	399999990	Part not needed	
29	1	630820000	Collet 6mm with flange nut (double flat)	
30	1	316062270	BÆRING SXE	24
31	1	344099140	Buffer	13
35	1	338057490	Rating plate	11
36	1	399999990	Part not needed	
61	1	316065220	Spindle head compl.	33
62	1	143115930	KUGLELEJE 6001	19
63	1	143111090	KUGLELEJE 6200	24
64	1	141180370	Retaining ring	11
65	1	143115490	Compensating washer	11
66	1	341071300	Coupling	18
70	1	143115470	Compensating washer	11
71	1	316051700	VENTILATORVINGE	17
75	1	316059800	Spindle lock	21
80	1	330002060	Fan	14
98	2	143195530	O-ring	11
1001	1	338505710	Wiring diagram	

