



| Position | Amount | Type number | Description | PG |
|----------|--------|-------------|---------------------------------------|----|
| 1 | 1 | 316043680 | Handle half compl. | 19 |
| 2 | 1 | 342022140 | Torsion spring | 11 |
| 3 | 1 | 316042960 | Screw set | 22 |
| 4 | 1 | 343394670 | Switch lock | 11 |
| 5 | 1 | 343408770 | Switch,120V | 21 |
| 6 | 1 | 344098340 | Switch guard | 11 |
| 7 | 1 | 338049710 | NAME PLATE | 11 |
| 9 | 1 | 311010890 | Field coil assembly w.field coil,120V | 36 |
| 10 | 1 | 143114860 | Ball bearing , | 22 |
| 11 | 1 | 343394600 | Baffle | 11 |
| 12 | 1 | 344098370 | Rubber ring | 11 |
| 13 | 1 | 310009350 | Armature compl. 120V | 37 |
| 14 | 1 | 344098350 | Cable sleeve,230V | 26 |
| 15 | 1 | 344098360 | Cable sleeve,120V | 11 |
| 16 | 1 | 344098380 | Rubber plug | 11 |
| 17 | 1 | 143115100 | Ball bearing, 15X 35X 11 | 19 |
| 18 | 1 | 399999990 | Part not needed | |
| 19 | 1 | 316043690 | Handle compl. | 14 |
| 21 | 1 | 315416390 | Motor bracket | 31 |
| 22 | 1 | 143114040 | Ball bearing, 10x26x8 | 22 |
| 23 | 1 | 341147850 | Key | 11 |
| 25 | 1 | 341201020 | Gear wheel | 22 |
| 26 | 1 | 344098320 | Ring | 11 |
| 27 | 1 | 315416380 | Gear box cover | 14 |
| 28 | 1 | 143110460 | Ball bearing, 17x40x12 | 25 |
| 29 | 1 | 341005750 | Spacer sleeve | 11 |
| 31 | 1 | 341005760 | Spacer sleeve | 13 |
| 32 | 1 | 141180110 | Retaining ring | 12 |
| 33 | 2 | 341031980 | Flange | 18 |
| 34 | 1 | 341012990 | Supporting disc | 11 |
| 35 | 1 | 339203110 | Wheel guard compl. | 33 |
| 36 | 1 | 341032010 | Flange protection | 11 |
| 37 | 1 | 343394620 | Motor housing cover | 15 |
| 39 | 2 | 343000940 | Cover cap for Kohlebuersten | 11 |
| 40 | 1 | 316042980 | Carbon brush set,120V | 19 |
| 41 | 2 | 343000930 | Brush holder | 17 |
| 42 | 1 | 343394610 | Motor housing | 25 |
| 43 | 1 | 341515330 | Connector bolt | 14 |
| 44 | 1 | 343394570 | Stop gauge | 20 |
| 48 | 1 | 316043700 | Locking bolt compl. | 13 |
| 54 | 1 | 316043720 | Spindle stop compl. | 11 |
| 56 | 2 | 338121160 | Metabo label | 11 |
| 57 | 1 | 342050850 | Spring | 18 |
| 58 | 1 | 341520180 | Bolt | 16 |
| 60 | 1 | 344098330 | Cable sleeve | 11 |
| 63 | 1 | 339160780 | GUARD PLATE | 16 |
| 65 | 1 | 344530790 | Cable w.UL/CSA-plug | 29 |
| 66 | 1 | 338121170 | Indication label | 11 |
| 69 | 1 | 341147840 | Spindle | 19 |
| 70 | 1 | 339133390 | Clamping Jaws | 20 |
| 71 | 1 | 343394580 | Threaded spindle holder | 16 |
| 72 | 1 | 339133420 | steelplate | 11 |

| Position | Amount | Type number | Description | PG |
|----------|--------|-------------|---------------------|----|
| 74 | 1 | 341515360 | Depth stop | 16 |
| 75 | 3 | 344098280 | Rubber foot | 11 |
| 76 | 1 | 339133410 | Base table | 32 |
| 77 | 1 | 344163520 | Spanner Kentool | 13 |
| 78 | 1 | 343394890 | Dummy plug | 11 |
| 79 | 1 | 399999990 | Part not needed | |
| 80 | 1 | 399999990 | Part not needed | |
| 81 | 1 | 399999990 | Part not needed | |
| 82 | 1 | 316043800 | Spindle compl. | 30 |
| 83 | 3 | 344098550 | Rubber plug | 12 |
| 84 | 1 | 143195240 | Gasket | 11 |
| 880 | 1 | 344131180 | Grease Tube | 11 |
| 1001 | 1 | 338504540 | Wiring diagram,120V | |

