



| Pozitie | Cantitate | Numar tip | Denumire | PG |
|---------|-----------|-----------|-------------------------------|----|
| 2 | 7 | 141113180 | Self-tap. fill. h. screw | 11 |
| 4 | 1 | 316051260 | Gear-box compl. Quick | 47 |
| 6 | 2 | 141119850 | Fillister head screw | 11 |
| 8 | 1 | 317004160 | Motor, 18 V (LT) | 43 |
| 9 | 1 | 316050450 | Switch slide compl. | 12 |
| 10 | 1 | 343431110 | Housing w.cover | 26 |
| 11 | 1 | 342021670 | Spring clip | 11 |
| 12 | 1 | 343430890 | Switch slide,R/L | 11 |
| 14 | 1 | 343397990 | Pressure plate | 11 |
| 15 | 1 | 343394790 | Switch slide | 11 |
| 16 | 1 | 343410630 | Switch | 30 |
| 17 | 1 | 338058370 | Rating plate | 11 |
| 25 | 1 | 143160080 | Toroidal Ferrite OD11.5*ID5*9 | 13 |
| 26 | 1 | 343083380 | LED lense | 13 |
| 27 | 1 | 339137270 | Hook | 13 |
| 30 | 1 | 343448690 | bit-depot 18 V | 13 |
| 95 | 1 | 343439680 | Cover cap | 11 |
| 850 | 1 | 627240000 | Chuck Futuro Plus S1M Quick | |
| 1001 | 1 | 338504870 | Wiring diagram | |

