



Pozitie	Cantitate	Numar tip	Denumire	PG
1	1	316097440	Gear housing compl.	27
2	1	316040610	Spindle stop compl.	14
3	4	141120070	Fill. head screw	11
4	4	141123940	Self-tap. fill. h. screw	11
5	1	316097430	Flange compl.	30
6	1	339013130	Compensating Washer	11
7	1	316097550	Bevel gear and pinion	24
8	1	344103340	O-ring	11
9	1	341166740	Spindle	18
10	1	339007790	Washer	11
11	1	143192540	O-ring	11
12	1	341102660	Hex nut M7	11
13	1	143116270	Ball bearing, 8x22x 7	15
14	1	141156650	Retaining ring	11
15	1	339007940	Washer	11
16	1	339153550	Baffle	11
17	1	310012720	Armature compl.,230V	32
18	1	343392740	Sealing washer	16
19	1	143115870	Ball bearing, 6x19x6	15
20	1	344114190	Rubber bushing	11
21	1	339151290	Baffle	11
22	1	314000540	Handle cpl.	22
23	1	311012800	Field coil compl.,230V	29
24	1	315013930	Motor housing	20
25	1	338070250	Rating plate	13
26	1	316097600	Brush holder compl.	21
27	1	343013500	Carbon Brush 230V	19
28	1	141116020	Self-tap fill h screw	12
29	1	343362490	Cable clip	12
30	1	343447070	Motor Cap with EU	16
32	2	141118730	Self-tap. fill. h. screw	11
33	1	343446380	Cable sleeve	11
34	1	344499540	Cable w.CEE plug	23
35	1	343446480	Switch rod	11
36	1	343437100	Switch slide	11
37	1	338122540	Metabo plate	11
38	1	343411110	Switch,FPCe 230 V	26
39	1	339209540	Wheel guard compl.,Ø115	20
40	1	141124060	Fillister head screw	11
41	1	341031160	Clamping flange	22
42	1	341106900	Flange nut	20
43	1	344163920	Pin spanner	14
880	1	344130910	Grease 100G	24
1001	1	338504470	Diagram	

