



Pozitie	Cantitate	Numar tip	Denumire	PG
1	4	341723170	Self-tap. fill. h. screw	11
2	1	343448230	Press button	11
3	1	342024350	Pressure spring	11
4	1	316097750	Gear housing compl.	32
5	1	344071130	Felt washer	11
6	1	341109130	Hex nut	12
7	1	320054450	Ball bearing	19
8	1	344114080	Sealing ring	12
9	1	341020220	Washer	11
10	1	342024300	RETAINING RING	12
11	1	339153570	Baffle	13
12	1	310150120	Armature 110V	41
13	1	339153580	Baffle	13
14	1	314000280	Handle cpl.	25
15	1	141180060	RETAINING RING	11
16	2	141123890	Fillister head screw,(DIN 7985)	11
17	1	339149180	Bearing cover	12
18	1	320054460	Ball bearing	20
19	1	344071140	Felt	13
20	1	341605680	Spindle	21
21	1	339013190	Sealing washer	12
22	1	315203160	Gear flange	25
23	4	141121640	Fill. head screw(DIN 7985)	11
24	1	141114010	Cheese-head screw	11
25	1	339204880	Wheel guard compl.	26
26	1	399999990	Part not needed	
27	1	399999990	Part not needed	
28	1	341519740	Locking bolt	13
29	1	316097770	Bevel gear and pinion D230	32
30	1	311013030	Field,120V-127V	41
31	1	344114090	Dust seal	12
32	1	320054470	Ball bearing	16
33	1	343448240	Motor housing	29
34	2	316097780	Carbon brush holder compl.	18
35	3	341723070	PAN HD.PLASTIC SCR.	11
36	1	316097790	Carbon brush compl.	16
37	2	343448260	Brush holder cover	13
38	6	341723190	Self-tap. fill. h. screw	11
39	1	338129850	Metabo label	12
40	1	343409150	Switch,230V/120V	26
41	2	344114110	Sleeve,120V	11
43	1	343448330	CABLE CLIP	11
44	1	344114120	Cable sleeve	12
45	1	343448250	Carry Handle (B)	20
46	1	343448270	Carry Handle (A)	20
47	1	344531880	Cable,120V	31
48	1	338070630	Rating plate	12
50	1	338122090	Warning Label 52x22	11
51	1	399999990	Part not needed	
880	1	344130910	Grease 100G	24
1001	1	338502110	Diagram	

